

UNCLASSIFIED

**DOC-003, Rev -**Written by: Emma Ployee
Reviewed by: R. Stamp**Inspect Outgoing Product**Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

Inspect Outgoing Product

DOC-003

Revision -

Written by:
Emma PloyeeReviewed by:
R. Stamp

--	--

BUSINESS CONFIDENTIAL AND STRATIVUS GROUP PROPRIETARY: Not for public release; distribution is limited to intended parties who receive this document directly from Strativus Group or its agents. Material and information relates to, or is associated with, Strativus Group or affiliates' products, business, or activities, including but not limited to financial information, data or statements, trade secrets, product research and development, existing and future product designs and performance specifications.

NO-AI: This certifies that this document has been created without the use of generative Artificial Intelligence (AI). This statement removes any doubt: this process was written by a human. All sections and steps in this process are the original thoughts of a team of humans, including the Author and Reviewer named in the signature block above.

UNCLASSIFIED

UNCLASSIFIED



DOC-003, Rev -

Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

Revision Table for DOC-003 "Inspect Outgoing Product"

Rev	Description of Change
(current) -	<i>First formal release</i>

UNCLASSIFIED

UNCLASSIFIED

**DOC-003, Rev -**

Written by: Emma Ployee

Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product

3 named resources are identified to perform this process

Requirements Table for DOC-003 "Inspect Outgoing Product"

Successful execution of this procedure produces evidence of verification for the requirements listed in the table below. Therefore, this procedure's execution is particularly important for us to achieve our goal. When you see procedure call-outs in this style of box, that step is what produces this critical evidence. Take the time to understand how these requirements will be verified prior to starting this procedure, and consult this procedure's author (Emma Ployee) if necessary.

RID	Text of Requirement	Verif. Method	Step
R001	The cube shall have beveled edges	Inspection	Step 1.2

UNCLASSIFIED

UNCLASSIFIED

**DOC-003, Rev -**

Written by: Emma Ployee

Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product

3 named resources are identified to perform this process

DOC-003, Rev - "Inspect Outgoing Product"

- [Section 1](#): Hello World! This will render as the text for Section 1.
 - [Step 1.1](#): Hello World! This will render as the text for Step 1.1.
 - [Step 1.2](#): Since this step follows, it will be Step 1.2
- [Section 2](#): Tables!
 - [Step 2.1](#): Embedded CSV data in the EBML file
 - [Step 2.2](#): External CSV files can be imported as tables
- [Section 3](#): Clean up
 - [Step 3.1](#): Document everything we just did
 - [Step 3.2](#): Notify the team

⚠ Electrostatic Discharge (ESD) Risk: Observe precautions for handling electrostatic sensitive devices.

⚠ This procedure is executed on flight hardware in a cleanroom environment. All factory cleanroom policies apply, including 'top-down' application of head and body garments to maintain the certified cleanliness levels of the work area(s). All personnel intending to touch flight hardware must wear gloves.

UNCLASSIFIED

UNCLASSIFIED

**DOC-003, Rev -**

Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product


Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

This process has 2 stated objectives:

1. Have clean hands (Step 3.1)
2. Keep a complete log in the lab of all activities, including this one (Step 3.1)

This process has 3 *Out Of Scope* declarations:

- ⊕ This process uses only one computer to perform these tasks. For parallel quantum computing, see the other department's procedure. (Step 1.2)
- ⊕ Do not perform additional testing to verify the requirement above. Inspection of the results is the only thing we're being paid for here, per contract clause 18.9.3.4(a).10.XV(g). Violators must pray to the charge number gods to receive an overhead number when re-submitting your timesheet in triplicate! OBEY! (Step 1.2)
- ⊕ This procedure does not do all of your company emailing for you. It only instructs you to send this one email. (Step 3.2)

"Inspect Outgoing Product" applies to *Product* to produce *Inspected Product***3 named resources are identified to perform this process:****Step 1.1**

Screwdriver, Phillips
Head #2

Step 1.1

Laptop with WiFi
disabled in BIOS by
Security Team

Step 1.2

Computer

Equipment Calibration Status

Equipment	Model Number	Serial	Last Cal Date	Valid Until
Screwdriver, Phillips Head #2				

If any equipment is within 30 days of needing recalibration, notify your QA rep.

Today's Date:

UNCLASSIFIED

UNCLASSIFIED



DOC-003, Rev -

Written by: Emma Ployee

Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product

3 named resources are identified to perform this process

UNCLASSIFIED

UNCLASSIFIED



DOC-003, Rev -

Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

Log of Non-Conformances during this execution:

Time	Step	Record	Brief Summary of Observation(s) that Deviated from Documented Expectations

UNCLASSIFIED

**DOC-003, Rev -**

Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

Section 1: Hello World! This will render as the text for Section 1.

☐ Step 1.1: Hello World! This will render as the text for Step 1.1.

2 named resources are identified to perform this step:

Screwdriver, Phillips
Head #2

Laptop with WiFi
disabled in BIOS by
Security Team

⚠ You should replace these placeholders with process information!



Action to perform	Expected	Result	Done	TPV
Do this	Expect this		☐	☐
Do this other thing	Expect this other result		☐	N/A

UNCLASSIFIED

**DOC-003, Rev -**Written by: Emma Ployee
Reviewed by: R. Stamp**Inspect Outgoing Product**Applies to Product to produce Inspected Product
3 named resources are identified to perform this process☐ **Step 1.2: Since this step follows, it will be Step 1.2****1 named resources are identified to perform this step:****Computer**

⚠ **Out-of-Scope Caution:** This process uses only one computer to perform these tasks. For parallel quantum computing, see the other department's procedure.

Lorem ipsum dolor sit amet, consectetur adipiscing elit. Curabitur sagittis tellus id arcu molestie mollis. Sed pretium aliquam odio, sed sagittis velit hendrerit ut. Donec vel feugiat nulla, ut laoreet lectus. In lobortis, libero a maximus venenatis, libero neque rutrum nisl, nec consequat arcu enim in dui. Cras tortor sapien, aliquet eu metus in, mattis consectetur magna. Praesent at congue mauris. Donec aliquam nisi in ex efficitur, et varius urna suscipit. Donec quis leo odio. Pellentesque sit amet ex at lorem sagittis posuere.

Action to perform	Expected	Result	Done	TPV
Use the computer to issue the commands below	The cube now has bevels		☐	N/A

```
> cd /etc  
> ./cubestuff --bevel cube.stp
```

This step produces the evidence of verification for this requirement:

R001: "The cube shall have beveled edges" (Verify by Inspection)

Please ensure the evidence produced passes the requirement before proceeding. This might require consulting this procedure's author, Emma Ployee.

⚠ **Out-of-Scope Caution:** Do not perform additional testing to verify the requirement above. Inspection of the results is the only thing we're being paid for here, per contract clause 18.9.3.4(a).10.XV(g). Violators must pray to the charge number gods to receive an overhead number when re-submitting your timesheet in triplicate! OBEY!

UNCLASSIFIED

**DOC-003, Rev -**

Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

3000 x 3000 px
placeholderImage-large.png

Pixel boxes are 30 x 30 px

To replace this with another
image, place the image file
in the Process folder, and
reference it in EBML:

Image | myFile.png | Caption!

This is what it should look like at the end of this step

**DOC-003, Rev -**

Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product

Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

Section 2: Tables!

☐ Step 2.1: Embedded CSV data in the EBML file

This is the table caption

Header Column 1	Header Column 2
Data Row 1 Col 1	Data Row 1 Col 2
Data Row 2 Col 1	Data Row 1 Col 2

☐ Step 2.2: External CSV files can be imported as tables

The "CSV File" line below is commented out in the EBML file, because it's referencing a CSV file that (presumably) doesn't exist.



DOC-003, Rev -
Written by: Emma Ployee
Reviewed by: R. Stamp

Inspect Outgoing Product
Applies to Product to produce Inspected Product
3 named resources are identified to perform this process

Section 3: Clean up

☐ Step 3.1: Document everything we just did

Action to perform	Expected	Result	Done	TPV
Sign the log	Log is signed, with additional room for more signatures from future operators		☐	N/A
Wash your hands	TPV		☐	N/A

★**Objective Achieved:** Have clean hands

★**Objective Achieved:** Keep a complete log in the lab of all activities, including this one

☐ Step 3.2: Notify the team

Action to perform	Expected	Result	Done	TPV
Email distribution@company.com with subject "PROCEDURE DONE"	Email goes from Outbox to Sent		☐	N/A
Do the workflow thing in Slack or whatever	Slack gives confirmation		☐	N/A

⚠ **Out-of-Scope Caution:** This procedure does not do all of your company emailing for you. It only instructs you to send this one email.